Bruhath Bangalore Mahanagara palike,

Inspection Report

1	Name of work	Construction of Bridge over Storm Water Drain at 12th C Main Road Mutyala Nagara in JP Park Ward No.17
2	Administration Approval & Date	JC/RRN/AS/2805/13-14 Dtd 18-01-2014 by JC (RRN)
3	Technical Sanction Estimate No & Date	EE/RRND/TS/289/13-14 Dtd:18-01-2014 by EE (RRND)
4	Estimate Amount	Rs.19.99 Lakhs
5	Job Code No.	017-14-000099
6	P-Code	P2434
7	Agreement No & date	EE/RRND/AG No./257/2013-14 Dtd.20-02-2014
8	Work order Number & Date	EE/RRND/W.O/257/2013-14 Dtd.20-02-2014
9	Contract Amount as per Agreement	Rs.20,83,676/-
10	Bill Amount	Rs.20,79,745/-
11	B.R. No. & Date	64/2015-16 dt.31-07-2015
12	Agency	M/s. J.C.Prakash
13	M.B. Number & Page No. of Measurement recordes	174/2013-14 Pages to 17301 to 17311
14	Date of Inspection	29-05-2016
15	Enclusures	1) Extract of MB No.174/13-14 Page 17311/2 2)4 Number of photos taken during inspection of above site
16	Inspection Report	I have Inspected the above site Location along with the Conservancy Supervisor. The measurements of the Items which are susceptible for measurements have been checked and found to be satisfactory

EE (RRND) RR Nagara

29/5/2016
(R.Sathyanarayana)
Inspection Report officer,

Scanned by CamScanner